Approved For Release 2003/11/25: CIA-RDP75B00285R009600090016-3

SECRET

25X1

IDEA-0132-70 Copy / of 7

28 April 1970

MEMORANDUM FOR THE RECORD

SUBJECT: Trip Report - 21-24 April 1970

Distribut AMA/OSA	ion 6 MAY 1970
1323	
3 %	Ø
Pile D	edirey
Tickler_	0 ther_

1. Location and Purpose of Visit:

The undersigned visited Detachment "G" from 21-24 Apeil 1970 to witness ejection-seat canopy-breaker test performed by LAC to qualify new canopy-breaker bar.

2. Results of Visit:

Gross observation indicates that the objectives of the ejection-seat test firing were met. A more accurate appraisal will be made after inspection of the filmed sequence from the various angles.

Of major concern during this test firing was the failure of the personnel parachute. Two (2) previous test firings over a year ago were both successful, however, the S1010 PPA was not on the dummy. A training S1010 PPA suit mated to an RQ 225 parachute like the operational parachute was utilized for this test. It should be pointed out that parts to prepare this test parachute were, in some cases, beyond shelf life and in others, salvaged from earlier ejections, since new parts were not available.

SECRET

25X1

	Approved For Release 2003/11/25 : CIA-RDP75B00285R00000000016-3	
	SECRET	25X1
	IDEA-0132-70 Page 2	
25X1	As a result of this ejection failure, a one-time inspection is being accomplished by LAC on all operational parachutes, the problem having been identified and discussed in message traffic. See Attachment. A second test firing with a cold soaked canopy will be performed on 6 May 1970 utilizing the S1010 PPA suit and an operational RQ 225 parachute.	25X1
	Attachment As stated above AMS/OSA	25X1
25X1	CONCURRENCE AND/OR COMMENTS 28 Cp. 70 C/AMS/OSA Date	
25X1	AMS/OSA (28 Apr 70) Distribution 1 - AMS/OSA (28 Apr 70) 1 - AMS/OSA (27 Apr 70) 2 - (28 Apr 70) (28 Apr 70)	

SECRET 25X1



Approad For Release 2003/11/25 : CIA-RDP75B00285R000300090016-3

SECRET

(When Filled In) FILE INFO

	27 AP	RI073772	REPRODUC	CTION PROHI	BITED	774 . ec 67 missed	Figure 2011 of 13
ACTION	1	Maria	6	TO EA	11	16	
	2	JIII	7	11	12	17	
	3	1	3	1177-	13	18	
25X1	4	MIDDE	9	647	14	19	
	5	NISA	1ø 'y	1005	15	2ø	

Distribution

AMA/OSA APR 1970

25X1NS E C R E T 2717282 APR 70

IDEALIST LIFE SUPPORT DM-1 SPO

25X1.

DTD 24 APR 70

SUBJ: PARACHUTE DROUGE GUN SEAR AND ARMING CABLE

25X1_{TN}:

EWC ESM HOUSING/CONDUIT INSPECTION File Destroy Tickler

- SEVEN CHUTES HAVE BEEN INSPECTED AND ALL WERE FOUND TO BE COMPLETELY OPERABLE/SAFE. ONE HOUSING ASSEMBLY WAS FOND TO BE OUTSIDE DRAWING TOLERANCE. HOWEVER, IN COMBINATION WITH THE DROUGE GUN, THE ASSOCIATED SEAR WOULD OPERATE PROPERLY IN THE HOUSING. THIS HOUSING ASSEMBLY WAS REPLACED.
- 2. A NEW DROUGE GUN. JUST RECEIVED WAS CHECKED AND FOUND TO HAVE ITS SEAR (PIN) OUT OF TOLERANCE (TOO LARGE DIA.). THIS CONDITION WOULD HAVE BEEN FOUND DURING NORMAL INCOMING CHALITY CONTROL INSPECTION AND ALSO UPON ANY ATTEMPT TO ASSEMBLE II WITH THE HOUSING ASSEMBLY.

25X1 3. RECOMMENDS THAT PROJECT AND SPO SEND ALL CHUTES BACK THRU THE FACTORY FOR A ONE-TIME INPECTION OF

2ø

Approved For Release 2003/11/25 CIA-ROP75B00265R000300090016-3

SECRET

25X1 PAGE 2 SECRET

THE HOUSING ASSEMBLY AND DROUGE GUN SEAR.

X1 4. DOES NOT REGARD THIS AS A SAFETY OF FLIGHT

REQUIREMENT BUT RATHER AS A ONE-TIME INSPECTION BASED UPOR

THE FAILURE EXPERIENCED DURING RECENT CANOPY BREAK-EJECTIONS

TEST PER REF MESSAGE.

SECRET

ВТ

SECRET

	4 Apr 70 7	REPRODU	ICTION PROHIBI	TED			man 数
ACTION	1 1	6		11	\mathcal{L}^{T}	16	
	2	7 7	17 J. T. L.	12		17	
	3	8		13	, , , , , , , , , , , , , , , , , , , ,	18	
751	4	9		14		19	
	5	1ø		15		2ø	
NNNS E C R E	T 24234	2Z APP 76 CITE					25
IMMEDIATE							

LIFE SUPPORT

EYES ONLY FOR

NO NIGHT ACTION

RQ-225-3 PARACHUTE PROBLEM

THE FOLLOWING IS THE STATUS OF ALL THE HQ-225 PANACHUTES BELONG-ING TO ALL PARACHUTES LISTED ARE NOT TO BE CONSIDERED SERVICEABLE UNTIL NOTIFIED BY SERIAL NUMBER THAT THEY ARE

TO BE RETURNED TO SERVICE.

NUMBER	LOCATION	STATUS	DUE REPACK	REMARKS
122	H	NEEDS INSP	8 JULY 70	ENROUTE H-
	•	5. 5.		SHIP TO G
118	LAC	NEEDS INSP	DIJE	RETURN TO 6
120	H .	NEEDS INSP	DUE	RETURN TO G
152	Н	NEEDS INSP	12 MAY 70	RETURN TO G
83	LAC	NEEDS INSP	13 JUN 70	HETURN TO G
84	LAC	NEEDS INSP	DIJE	SHIP TO H
166	LAC (PMD)	NEEDS INSP	3 MAY 70	SHIP TO LAC-
				BURBANK-RETURN
				TO LAC (.0.5)
135	LAC	NEEDS INSP	18 JUN 70	RETURN TO G

Approved For Release 2003/11/25 : CIA-RDP75B00285R000300090016-3

WILL BE SHIPPED TO

LAC 25 APR 70-KE-

NEEDS INSP 17 JUN 70

25X1

•		•			
•		•	v	_	
	E	L .	п.	E	

ACTION 1 6 11 16 2 17 17 12 17 17 18 18 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	FILE INFO	(When Filled In)		
ACTION 1 2 7 12 17 3 8 13 18 4 9 14 19 19 10 MAN/OSA DATE 27 APR 1970 JEE DIF QTB DIF DIF QTB DIF DIF QTB DIF DIF DIF DIF DIF DIF DIF DI	24 hrt. 10 / 3683	REPRODUCTION PROHIBI	TED	
2 7 7 12 17 18 18 18 18 19 14 19 19 19 19 19 19 19 19 19 19 19 19 19		6	11 (, , , ,	16
HANS E C R E I 242102Z APR 70 CITE LIFE SUPPORT DY-1 UBJ: PERSONNEL PARACHUTE DEPLOYMENT FAILURE ESM File Destroy	2	7	13	17
Distribution AMA/OSA DATE 27 APR 1970 JEE DF UBJ: PERSONNEL PARACHUTE DEPLOYMENT FAILURE ESM File Destroy	3 ,	8	13	18
Distribution AMA/OSA DATE 27 APR 1970 JEE DF UBJ: FERSONNEL PARACHUTE DEPLOYMENT FAILURE ESM File Destroy	4	9	14	19
LIFE SUPPORT DY-1 UBJ: PERSONNEL PARACHUTE DEPLOYMENT FAILURE ESM File Destroy		10	15	20
1 IN:	LIFE SUPPORT DY- UBJ: PERSONNEL PARACHUT	-1 TE DEPLOYMENT FAILUR	DF QTB DOST	

- DEPLOYMENT FAILURE OF THE CHUTE WAS CAUSED AS FOLLOWS:
- THE SEAR (PIN) OF THE DROUGE GUN ASSEMBLY WAS ON THE HIGH SIDE BUT WIHIN ITS DIAMFTER TOLERANCE.
- B. THE CABLE CONDUIT SLEEVE PIN MARIS96-3 IN WHICH THE PIN SLIDES WAS TAPERED SUCH THAT IT WAS UNDER TOLERANCE VEAR END OF PIN TRAVEL.
- C. THE RESULT WAS THE PIN JAMMED IN THE SLEEVE PRIOR TO RELEASE OF THE DROUGE GUN FIRING MECHANISM. (THE 1/16 IN CABLE BROKE - 480 POUND PULL).
- E. THE CORRECTIVE ACTION IS TO ONE IME INSPECT ALL PARACHUTES TO ASSURE THE PROPER DIMENSIONS OF PIN AND SLEEVE TO PROVIDE PROPER CLEARANCE AND FUNCTION.
- THE ABOVE INPECTION WILL BE PERFORMED ON AU EXPEDITED BASIS.

25X1 🚛 WILL BE NOTIFIED IMMEDIATLEY IF ANY SEAR (PIN) OR CONDUIT SLEEVE FOUND TO BE OUT OF TOLERANCE ON THOSE PERSONNEL PARACHUTES TESTED.

SECRET

Approved For Release 2003/11/25: CIA-RDP75B00285R000300090016-3

SECRET

FILE INFO

BT

(When Filled In)

ACTION	1	. 6		11	16	
	. 2	7		12	17	
		8		13	18	
	5	9 1ø		14	19	
				15	2Ø	
PAGE 2		SECRET				
56	LAC	HEED'S INSP	18 JUN 79	RETURN T	0 G	
l65	Н	NEEDS INSP	12 MAY 70	RETURN T	0 G	
71	LAG	NEEDS INSP	9 JUN 70	RETURN T	0 G	
7.73	LAC	NEEDS INSP	DUF	in the second	\neg	25X
77	S	NEEDS INSP	DUE	WILL BE	SHIPPED TO	
				LAC 25 A	PR 70-RE-	
				TURN TO	3	
4	Н	NEEDS INSP	6 JUL 70			25X
				TO G	<u> </u>	
54	LAC	NEEDS INSP	30 APR 70	RETURN T	0 6	
79	H	NEEDS INSP	DUE	RETURN T	0 G	
57	LAC	NEEDS INSP	DUF		F.M.7	25X
2.	FOR	PARACHUTES 6	S/N 67, 80,	AND 84 ARE	BEING COURTERES)
o You	VIA			e e e e e e e e e e e e e e e e e e e	· · ·	25×
7 APRI	L 70. PLE	ASE RETURN YOUR	PARACHUTES	FOR INSPECT	ION VIA SAME	, r
OURIER		WILL BE	The second of th		किकार किन्द्राच्या करिया है। इ.स.च्या	
5. [<u> </u>	ILL HAVE SERVI	TARIT BADACU	LI. Hiteg an each	2 505	25
Ļ		Y, 25 APRIL 78.		ULED VE NAM) FUR	25
	umic Otiton	ise was monthly fine	•			

25X1

Approved For Release 2003/11/25 : CIA-RDP75B00285R000300090016-3